

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,277,051

USPTO CONFIRMATION CODE: 4868

APPLICATION NO.: 10/527,990

PCT FILED: September 30, 2002

US FILED: March 21, 2005

EXAMINER: Dao L. Phan

GROUP ART UNIT: 3662

FOR: METHOD AND A UNIT FOR BEAM CONTROL OF AN ARRAY ANTENNA

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION  
FOR USPTO AND/OR APPLICANT MISTAKE

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS


SIR:


The following is a request for a certificate of correction in Serial Number 10/527,990, now Patent Number 7,277,051.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 50-1379. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In Fig. 4A, Sheet 5 of 11, for Tag "401", delete "  and

insert - -  - -, therefor.

(AMENDMENTS TO THE DRAWINGS DATED APRIL 17, 2007, FIG. 4A, SHEET "5/11" TAG "401")

In Column 8, Line 22, delete "AND" and insert - - A/D - -, therefor.  
(INTERNATIONAL PUBLISHED APPLICATION, IN THE SPECIFICATION DATED MARCH 21, 2005, PAGE 14, LINE 11)

In Column 16, Line 27, delete "513" and insert - - 613 - -, therefor.  
(INTERNATIONAL PUBLISHED APPLICATION, IN THE SPECIFICATION DATED MARCH 21, 2005, PAGE 30, LINE 26)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

, 2008  
DATE

/SIDNEY L. WEATHERFORD, Reg#45602/

Sidney L. Weatherford  
Registration No. 45602

Attorney of Record